ሦ master ▼

...

advisories / CVEs / CVE-2021-40149.txt

MrTuxracer Minor fixes

Ax 1 contributor

```
83 lines (62 sloc) | 2.7 KB
                                                                                                                                                                               ...
      RCE Security Advisory
      https://www.rcesecurity.com
     1. ADVISORY INFORMATION
      -----
                      Reolink E1 Zoom Camera
      Product:
      Vendor URL:
                     https://reolink.com/product/e1-zoom/
                      Exposure of Sensitive Information to an Unauthorized Actor [CWE-200]
      Date found:
                      2021-08-26
 11
     Date published: 2022-06-01
      CVSSv3 Score: 7.5 (CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:N/A:N)
 12
                    CVE-2021-40149
     CVE:
 13
 14
      2. CREDITS
 17
      This vulnerability was discovered and researched by Julien Ahrens from
 18
 19
      RCE Security.
 20
 21
      3. VERSIONS AFFECTED
 23
      Reolink E1 Zoom Camera 3.0.0.716 (latest) and below
 24
 25
 26
 27
      4. INTRODUCTION
      Meet new generation of Reolink E1 series. Advanced features - 5MP Super
      HD & optical zoom are added into this compact camera. Plus two-way audio,
 31
      remote live view and more smart capacities help you connect with what you
 32
      care. Be closer to families and be away from worries.
 33
 34
      (from the vendor's homepage)
 36
 37
     5. VULNERABILITY DETAILS
 38
      The web server of the E1 Zoom camera through 3.0.0.716 discloses its SSL private
 39
 40
      key via the root web server directory.
 42
      An unauthenticated attacker can abuse this with network-level access to the
 43
      camera to download the webserver's private SSL key by simply going to the
 44
      following URL:
 45
      http://[CAM-IP]/self.key
 46
 48
 49
      6. RISK
 50
 51
      An unauthenticated attacker can download the webserver's SSL private key and
      thereby attack the encrypted network traffic to and from the camera, which might
 52
      lead to the disclosure of the administrative access credentials and other
      sensitive information.
 56
 57
     7. SOLUTION
 58
      -----
 59
      None.
 61
 62
     8. REPORT TIMELINE
 63
     2021-08-26: Discovery of the vulnerability
 64
      2021-08-26: Sent notification to Reolink via their support channel
 65
      2021-08-26: Response from vendor asking for vulnerability details
      2021-08-26: Sent all the vulnerability details
      2021-08-31: Vendor is still looking into the issue
 69
      2021-09-03: Vendor states that the issue will be fixed by the end of September.
 70
      2021-10-01: Since no firmware has been released, we've sent another notification
      2021-10-02: Vendor states that the new firmware is delayed
 71
      2022-02-01: Since there is still fix, sent another notification
      2022-02-02: Vendor states that the firmware with the fix hasn't been released yet.
      2022-03-03: Since there is still fix, sent another notification
 75
      2022-03-12: Vendor states they're still working on the issue (internal update awaits testing)
 76
      2022-05-24: Since there is still fix, sent another notification
      2022-05-24: Vendor states that the update still hasn't been released yet.
     2022-06-01: Almost a year should be enough to fix this. Public disclosure.
```