riscv-boom / riscv-boom Public

Code Sissues 64 Public Projects Projects Wiki •••

New issue Jump to bottom

## [Bug Report] Incorrect exception type of PMP violation during address translation #605

Open

Phantom1003 opened this issue on Jun 8 · 0 comments

## Phantom1003 commented on Jun 8

Type of issue: bug report

Impact: unknown

Development Phase: proposal

Other information

Our co-simulation framework found that the exception type of address translation PMP violation is incorrect.

In the following test case, we let a non-leaf (level 2) PTE out of the PMP range.

Next, we will perform a store operation with a special virtual address, during translation processor will try to access the PTE that does not match any PMP.

boom throws a store page fault(0xf), while spike throws a store access fault(0x7).

```
[boom] 3 0x0000000080000364 (0x0105051b) x10 0x0000000040201010
[boom] 3 0x0000000080000368 (0x02a00593) x11 0x000000000000002a
[spike] core 0: 0x0000000000000364 (0x0105051b) addiw
                                                    a0, a0, 16
           0: 0x0000000080000368 (0x02a00593) li
[spike] core
[boom] 3 0x0000000080000004 (0x34302f73) x30 0x0000000040201010
[spike] core 0: 0x00000000000036c (0x00b52023) sw
                                                   a1, 0(a0)
tval 0x0000000040201010
[spike] core 0:
[spike] core 0: 0x0000000080000004 (0x34302f73) csrr
                                                   t5, mtval
[boom] 3 0x0000000080000008 (0x34202f73) x30 0x0000000000000000f
[spike] core
             0: 0x0000000080000008 (0x34202f73) csrr
                                                   t5, mcause
[error] WDATA SIM 0000000000000007, DUT 0000000000000000
[error] check board clear 30 error
[CJ]
             0 integer register Judge Failed
```

According to riscv-privileged specification:

If accessing pte violates a PMA or PMP check, raise an access-fault exception corresponding to the original access type.

Hence, boom should throw a store access fault. Please tell us about your environment: - version: ad64c54 boom-1.zip @ProjectDimlight helps reproduce the problem cc to @jerryz123 Assignees No one assigned Labels None yet **Projects** None yet Milestone No milestone Development No branches or pull requests 1 participant

:P