Talos Vulnerability Report

TALOS-2020-1194

Micrium uC-HTTP HTTP Server null pointer dereference denial-of-service vulnerability

JANUARY 26, 2021

CVE NUMBER

CVE-2020-13583

Summary

A denial-of-service vulnerability exists in the HTTP Server functionality of Micrium uC-HTTP 3.01.00. A specially crafted HTTP request can lead to denial of service. An attacker can send an HTTP request to trigger this vulnerability.

Tested Versions

Micrium uC-HTTP 3.01.00

Product URLs

https://www.micrium.com/rtos/tcpip/

CVSSv3 Score

8.6 - CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:C/C:N/I:N/A:H

CWE

CWE-476 - NULL Pointer Dereference

Details

The uC-HTTP server implementation is designed to be used on embedded systems that are running the μ C/OS II or μ C/OS III RTOS kernels. This HTTP server supports many features including persistent connections, form processing, chunked transfer encoding, HTTP header fields processing, HTTP query string processing and dynamic content.

The HTTP server implementation provides compile time configuration options to enable HTTP Forms. By default the server will have this compiler option enabled but the developer is expected to set the FormCfgPtr structure at compile time. If this structure isn't set, then a denial of service exists due to a NULL pointer dereference when trying to access memory that is allocated based on the existence of the FormCfgPtr structure.

This code snippet shows the behavior of the code if the compiler flags HTTPs_CFG_FORM_EN and HTTPs_CFG_FORM_MULTIPART_EN are set, and the FormCfgPtr is NULL, memory will not be allocated for the FormBoundaryPtr variable. This snippet is from the function HTTPsMem_ConnGet

Later, when processing Content Type multipart, the code attempts to place a null character at the end of a string pointed to by the pointer FormBoundaryPtr. The code does not check for a NULL pointer for either of the values FormCfgPtr or FormBoundaryPtr, which results in a NULL pointer dereference when FormBoundaryPtr is used. This is a code snippet from the function HTTPsReq_HdrParse

Crash Information

```
Program received signal SIGSEGV, Segmentation fault.
HTTPsReq_HdrParse (p_err=0xffffcd48, p_conn=0x565a7708 <Mem_Heap+1352>, p_instance=0x565a71dc <Mem_Heap+28>) at http-s_req.c:1664
1664
(gdb) bt
#HTTPsReq_HdrParse (p_err=0xffffcd48, p_conn=0x565a7708 <Mem_Heap+1352>, p_instance=0x565a71dc <Mem_Heap+28>) at http-s_req.c:1664
#H HTTPsReq_HdrParse (p_err=0x565a71dc <Mem_Heap+28>, p_conn=0x565a7708 <Mem_Heap+1352>) at http-s_req.c:325
#2 0x56560ea2 in HTTPSConn_Process (p_instance=0x565a71dc <Mem_Heap+28>) at http-s_conn.c:159
#3 0x56564c21 in HTTPSTask_InstanceTaskHandler (p_instance=0x565a71dc <Mem_Heap+28>) at http-s_task.c:814
#4 HTTPsTask_InstanceTask (p_data=0x565a71dc <Mem_Heap+28>) at http-s_task.c:553
#5 0x565653a3 in HTTPSTask_InstanceTaskCreate (p_instance=0x565a71dc <Mem_Heap+28>, p_err=0xffffce78) at http-s_task.c:331
#6 0x5655e96 in HTTPS_InstanceStart (p_instance=0x565a71dc <Mem_Heap+28>, p_err=0xffffce78) at http-s_task.c:811
#7 0x5655960 in main (argc=1, argv=0xffffcf44) at ../Examples/NoFS/app/app_no_fs.c:122
#8 0x56557326 in main (argc=1, argv=0xffffcf44) at ../Examples/NoFS/app/app_no_fs.c:133
```

Timeline

2020-11-02 - Vendor Disclosure 2021-01-22 - Vendor Patched 2021-01-26- Public Release

CREDIT

Discovered by Kelly Leuschner of Cisco Talos.

VULNERABILITY REPORTS PREVIOUS REPORT NEXT REPORT

TALOS-2020-1193 TALOS-2020-1190