New issue

Jump to bottom

Lack hardware wake-up support checking #78

⊘ Closed TheSilentDawn opened this issue on Oct 14, 2020 · 5 comments

Assignees

Labels

enhancement internal bug tracker mw usb

Projects

III stm32cube-mcu-fw-dashb...

Milestone

\$\Phi \text{v1.10.0}\$

TheSilentDawn commented on Oct 14, 2020 • edited ▼

Describe the set-up

- Software:
 - o STM32Cube MCU & MPU Packages
- Version:
 - STM32Cube_FW_H7_V1.8.0
- Verification Hardware Platform:
 - STM32H7B3

Describe the bug

- Function:
 - static void USBH_ParseCfgDesc(USBH_CfgDescTypeDef *cfg_desc, uint8_t *buf, uint16_t length)
- Location:
- Type:
 - O Denial-of-Service.
- Result:
 - The system will hang when trying to set a remote wake-up feature.
- Description:
 - o The function USBH_ParseCfgDesc() parses the configuration descriptor, interface descriptor, and endpoint descriptor by input data from a USB device.
 - o And it set the variable cfg_desc-> bmAttributes by the input data from the USB device. This variable will be used as part of a judgment in the function USBH_Process() as shown in

STM32CubeH7/Middlewares/ST/STM32_US8_Host_Library/Core/Src/usbh_core.c
Line 643 if ((phost->device.CfgDesc.bmAttributes) & (1U << 5))

. With a malformed value, the remote wakeup may be enabled as shown in

STM32CubeH7/Middlewares/ST/STM32_US8_Host_Library/Core/Src/usbh_core.c
Line 643 in 79196b0

643 if ((phost->device.CfgDesc.bmAttributes) & (1U << 5))

. If the hardware doesn't support this feature, the system will hang due to a FAIL return value by the function USBH_HandleControl().

How To Reproduce

- 1. Running MSC_Standalone application on the STM32H7B3I platform
- 2. Plug a USB disk
- 3. Use the attached Bug4.txt to replace the USB device packet. Bug4.txt

Additional context

• To patch it, the program should check if the hardware supports a remote wake-up feature.

[I] ALABSTM added this to To do in stm32cube-mcu-fw-dashboard on Oct 15, 2020

A RKOUSTM assigned ALABSTM on Nov 18, 2020

ALABSTM commented on Nov 24, 2020

Contributor

Hi @TheSilentDawr

Thank you for this other report. If I understood the idea we should ensure that the software embedded within the host checks whether the value bmAttributes provided by the device is correct? Which reference should the host base itself on to perform such a check? Should we not assume the data provided by the device is correct?

Otherwise, when to stop checking? In case the host has a reference to base itself on, then would it not also make sense to check the validity of this reference too?

I hope my questions make sense. My goal is to be sure I understood correctly your point before reporting it to our development teams. I am looking forward to reading your reply. Thank you again.

With regards,

TheSilentDawn commented on Nov 25, 2020 • edited 🕶

Author

Hi @ALABSTM,

No, I think the software embedded within the host should check if the hardware or the board supports or enables the wake-up feature. If not, the firmware shouldn't check bmAttributes as the current logic which will lead the whole system to hang. And to patch it, the wake-up feature checking codes should be added before the bmAttributes is accessed in the function and position reported upper. If anything not clear, please let me know. Thanks for your help.^_

ALABSTM commented on Dec 2, 2020

Contributor

Hi @TheSilentDawn,

Please allow me this couple of questions:

- Is there any way for the host to check whether the device supports the wake-up feature other than the bmAttributes read from the device descriptor?
- You mentioned "the wake-up feature checking codes". Are you referring to some piece of code already present in our source files that should be moved before the reading of the
 http://linear.px

Thank you,

- ALABSTM moved this from To do to Assigned in stm32cube-mcu-fw-dashboard on Dec 2, 2020
- National ALABSTM added the www label on Dec 2, 2020
- National ALABSTM added the enhancement label on Dec 15, 2020
- National Alabet Alabet Alabet on Jan 18, 2021
- ALABSTM moved this from Assigned to In progress in stm32cube-mcu-fw-dashboard on Jan 18, 2021
- National ALABSTM added the internal bug tracker label on Jan 18, 2021

ALABSTM commented on Jan 18, 2021

Contributor

ST Internal Reference: 99173

- ALABSTM added this to the v1.10.0 milestone on Feb 22, 2021
- ALABSTM moved this from In progress to To release in stm32cube-mcu-fw-dashboard on Feb 22, 2021
- ▼ TheSilentDawn mentioned this issue on May 31, 2021

No validity chekcing on the variable dev_desc->bMaxPacketSize #75

⊙ Closed

ALABSTM commented on Mar 14

Contributor

Hi @TheSilentDawn,

Hope you're fine. Just to inform you the fix has been published in the frame of v1.10.0 release.

With regards,

ALABSTM closed this as completed on Mar 14

[1] stm32cube-mcu-fw-dashboard automation moved this from To release to Done on Mar 14

Assignees



Labels

enhancement internal bug tracker mw usb

Projects

stm32cube-mcu-fw-dashboard

Done

v1.10.0

Development

No branches or pull requests

2 participants

