Openwall Products Services Publications Resources What's new

```
bringing security into 
open environments
Hash Suite - Windows password security audit tool. GUI, reports in PDF.
[<prev] [next>] [day] [month] [year] [list]
```

```
Date: Tue, 25 Feb 2020 19:04:01 +0100
From: Florian Weimer <Tweimer@..hat.com>
To: oss-security@..ts.openwall.com
Subject: CVE-2020-9391: Ignoring the top byte of addresses in brk causes heap corruption (AArch64)
AArch64 has an architectural feature where the top byte of a 64-bit pointer is ignored. Therefore, applications can use this as storage space for colored pointers without having to mask those bits. Recent Linux kernels (starting with 5.4) ignore the top byte in certain systecall arguments as well. This was also done for the brk system call, b there it can result in moving the brk in the wrong direction (downward instead of upward).
  Here's a test program that shows the problem with the glibc allocator on AArch64:
#include <err.h>
#include <stdlib.h>
#include <stdio.h>
#include <stddef.h>
#include <string.h>
   main (void)
      enum { size = 4096, count = 128 };
void *array[count];
for (int i = 0; i < count; ++i)</pre>
                array[i] = malloc (size);
if (array[i] == NULL)
  err (1, "malloc (%d)", size);
      void *p = malloc ((2ULL << 56) - size * count);
printf ("p = \$p\n^*, p);
if (p != NULL)
explicit_bzero (p, 1024);
       for (int i = 0; i < count; ++i)
            explicit_bzero (array[i], size);
      for (int i = 0; i < count; ++i)
  free (array[i]);</pre>
      free (p);
      return 0;
  With Fedora's 5.6.0-0.rcl.git0.1.fc32.aarch64 kernel, this is the result.
                                                                                                         = 0x2c490000
  brk (NULL)
  brk(0x2c4b1000)
                                                                                                          = 0x2c4b1000
                                                                                                          = 0x2c4b1000
  brk (NULL)
  brk (NULL)
                                                                                                          = 0x2c4b1000
  brk(0x2c4d2000)
                                                                                                          = 0x2c4d2000
  brk (NULL)
                                                                                                               0x2c4d2000
= 0x2c4f3000
brk(0x2c514000) = 0x2c514000
mmap(NULL, 144115188075335680, PROT_READ|PROT_WRITE, MAP_PRIVATE|MAP_ANONYMOUS, -1, 0) = -1 ENOMEM (Cannot allocate memory)
brk(0x20000002c4b1000) = 0x2c514000
mmap(NULL, 144115188075466752, PROT_READ|PROT_WRITE, MAP_PRIVATE|MAP_ANONYMOUS, -1, 0) = -1 ENOMEM (Cannot allocate memory)
--- SIGSECV (si signo=SIGSECV, si code=SECV_MAPERR, si_addr=0x2c510a98) ---
+++ killed by SIGSECV (core dumped) +++
 The last brk call moved the break down because the top byte has been ignored by the kernel. glibc detects the brk result as a failure, but at that point, the damage is already done, and the heap is corrupted.
 Originally reported by Victor Stinner as 
<a href="https://bugzilla.redhat.com/show_bug.cgi?id=1797052">https://bugzilla.redhat.com/show_bug.cgi?id=1797052</a>>. Additional analysis by DJ Delorie.
  The upstream fix is here:
  commit dcde237319e626dlec3c9d8b7613032f0fd4663a
  Author: Catalin Marinas <catalin.marinas@....com>
Date: Wed Feb 19 12:31:56 2020 +0000
            mm: Avoid creating virtual address aliases in brk()/mmap()/mremap()
           Currently the arm64 kernel ignores the top address byte passed to brk(), mmap() and mremap(). When the user is not aware of the 56-bit address) limit or relies on the kernel to return an error, untagging such pointers has the potential to create address aliasses in user-space. Passing a tagged address to mummap(), madvise() is permitted since the tagged pointer is expected to be inside an existing mapping.
            The current behaviour breaks the existing glibc malloc() implementation which relies on brk() with an address beyond 56-bit to be rejected by the kernel.
            Remove untagging in the above functions by partially reverting commit cel8d17lcb73 ("mm: untag user pointers in mmap/munmap/mremap/brk"). In addition, update the arm64 tagged-address-abi.rst document accordingly.
           Link: https://bugzilla.redhat.com/1797052
Fixes: cel8d17lcb73 ("mm: untag user pointers in mmap/munmap/mremap/brk")
Cc: <$table@...r.kernel.org> # 5.4.x-
Cc: Florian Weimer < Kweimer@...hat.com>
Reviewed-by: Andrew Morton <akpm@...ux-foundation.org>
Reported-by: Victor Stinner <vstinner@...hat.com>
Acked-by: Will Deacon <will@...nel.org>
Acked-by: Andrey Konovalov <andreyknvl@...gle.com>
Signed-off-by: Gatalin Marinas <catalin.marinas@...com>
Signed-off-by: Will Deacon <will@...nel.org>
```

<https://git.kernel.org/pub/scm/linux/kernel/git/torvalds/linux.git/commit/?id=dcde237319e626dlec3c9d8b7613032f0fd4663a>

Thanks, Florian

Powered by blists - more mailing lists

Please check out the Open Source Software Security Wiki, which is counterpart to this mailing list.

Confused about mailing lists and their use? Read about mailing lists on Wikipedia and check out these guidelines on proper formatting of your messages.

