## Talos Vulnerability Report

TALOS-2020-1140

## Schneider Electric EcoStruxure Control Expert PLC Simulator Modbus message processing remote code execution vulnerability

DECEMBER 8, 2020

CVE NUMBER

CVE-2020-7559

Summary

A code execution vulnerability exists in the Modbus message-processing functionality of Schneider Electric EcoStruxure Control Expert PLC Simulator 14.1. A specially crafted network request can lead to remote code execution. An attacker can send a large Modbus request to trigger this vulnerability.

Tested Versions

Schneider Electric EcoStruxure Control Expert PLC Simulator 14.1

Product URLs

https://www.se.com/ww/en/product-range-presentation/548-ecostruxure%E2%84%A2-control-expert/

CVSSv3 Score

10.0 - CVSS:3.0/AV:N/AC:L/PR:N/UI:N/S:C/C:H/I:H/A:H

CWE

CWE-121 - Stack-based Buffer Overflow

Details

EcoStruxure Control Expert (formerly UnityPro) is Schneider Electric's flagship software for program development, maintenance, and monitoring of industrial networks. To aid in the testing process of developed programs, a device simulator is included with Control Expert. When the simulator mode is started, it opens 0.0.0.0:502 on the host, allowing for communication with the simulator via Modbus.

When a large Modbus message is sent to this simulator, it is possible to write outside the bounds of a stack buffer, allowing for remote code execution.

In function sub\_1b48b00 a stack buffer of 0x8000 bytes is reserved to hold the Modbus message data. This buffer will be used as the dst argument of a subsequent memcpy call.

```
//
// sub_1b48b00
//
...
01b48be1 lea edx, [ebp-0x8004]  # allocate a stack buffer
01b48be7 push edx  # arg1
01b48be8 call sub_1b495c0  # call to vulnerable function
...
```

Execution continues into sub\_1b495c0 where the Modbus message to be processed is copied into the previously reserved stack buffer. This is done via a memcpy call with the following arguments:

dst: pointer to the stack buffer described above src: pointer to the head of the current Modbus message n : value pulled from the current Modbus message MBAP header length field

Since both the src and n arguments are determined by the user controlled Modbus message, and since there is no check to ensure that the message length is smaller than the buffer size, it is possible to use the memcpy call to write outside of the reserved buffer and gain execution through corruption of the program's exception handler.

## Crash Information

0:006> g

COMM Server Thread(1760.7c4): Access violation - code c0000005 (first chance)

First chance exceptions are reported before any exception handling.

This exception may be expected and handled.

eax=002af561 ebx=0029af16 ecx=00000001 edx=0000815d esi=002af560 edi=03550000

eip=6a4edf22 esp=0353fe20 ebp=0353fe40 iopl=0 nv up ei pl nz na po cy

cs=0023 ss=002b ds=002b es=002b fs=0053 gs=002b efl=00010203

MSVCR110!wcscpy\_s+0xb1:

6a4edf22 f3a4 rep movs byte ptr es:[edi],byte ptr [esi]

Timeline

2020-08-13 - Vendor Disclosure 2020-11-04 - CVE assigned 2020-11-09 - Vendor released 2020-12-08 - Public Release

CREDIT

Discovered by Alexander Perez-Palma and Jared Rittle of Cisco Talos.

VULNERABILITY REPORTS PREVIOUS REPORT NEXT REPORT

TALOS-2020-1126 TALOS-2020-1144