D-Link GO-RT-AC750 contains command injection vulnerability

overview

- · type: command injection Vulnerability
- supplier: D-Link (
- product: D-Link Go-RT-AC750

•

affect version: revA 1.01b03 & revB 2.00b02

The dlinkgo GO-RT-AC750 Wireless AC750 Dual-Band Easy Router is an affordable yet powerful wireless networking solution which combines the latest high-speed 802.11ac Wi-Fi specification with dual-band technology and fast Ethernet ports to deliver a seamless networking experience. The increased range and reliability of wireless AC technology reaches farther into your home, and the GO-RT-AC750's advanced security features keep your network and data safe from intruders.

Description

1. Vulnerability Details

the vulnerability is in /cgibin, hnap_main, the sprintf and system causes this vulnerability

```
if ( sub 41173C(v27, "/etc/templates/hnap//.shell action") )
       sprintf(v27, "sh %s%s.sh > /dev/console &", "/var/run/", v9);
       sprintf(v27, "sh %s%s.sh > /dev/console", "/var/run/", v9);
     system(v27);
we can control v9.
v5 = getenv("HTTP_SOAPACTION");
v6 = getenv("REQUEST_METHOD");
if ( v5 )
  if (!strstr(v5, "http://purenetworks.com/HNAP1/GetDeviceSettings") && sub_411490(v4) < 0 )
    cgibin_parse_request(0, 0, 0);
    v7 = -2;
    sub 4119C8():
    goto LABEL 36;
else
  V5 = "http://purenetworks.com/HNAD1/GatDavicaSattings"
v8 = strrchr(v5, '/'); Page
                           1 /
\sqrt{9} = \sqrt{8 + 1};
```