

## **Maximo Reporting**

## Status (ALL) Work Orders By Team

Team: 01005 - DIEMER UNIT

10 Total Team Work Orders

Report Date Ranges Are:

To: 06/19/2017

Start Date	Priority	WO #	Description	Craft	Estimated Labor Hrs	Actual Labor Hrs	Location
INPRG					10 Work Orders		
01/11/2017	1	13085231	Pump Main Gen. Fuel Trench		0.0	4.0	DFP-00050-0050
02/06/2017	1	104253T	Cip-104253 Task# Die-Treat; Diemer Administration Building Seismic Upgrades		1,400.0	0.0	DFP-00010
02/09/2017	1	103129C	Cip_103129 Basin Rehab Control System (Task# Dfc)		800.0	13.0	DFP
02/21/2017	1	13208123	Nitrogen Skid Trane 1 And 2 Is Faulted		0.0	4.5	DFP-00125-0800
02/21/2017	1	13207983	Oc-61 Meters Lost Power		0.0	17.0	LF
02/23/2017	3	13233025	Change Oil In Bearing Housings		0.0	53.0	DFP-00125-0260
02/23/2017	1	13228473	Sewer Lift Station Got Oil In It And Needs To Be Pumped Out		0.0	3.0	DFP-00360
05/18/2017	1	13489577	Install Receptace At East Filter Building		0.0	2.0	DFP-00090-0040
05/18/2017	4	13489578	Filter 8 Surface Wash Valve Not Working		0.0	20.0	DFP-00090-0160
05/31/2017	2	13539161	Sample Bearing Oil		0.0	51.5	DFP

Total: 2,200.0 168.0

Total for Team: 2200 168.0

Page 1 of 1 Tuesday, June 27, 2017