CANDLE CARE





Avoid excessive burn time, no more than 4 hours is recommended



Trim the wick to 1/4 " tall before every burn to keep the wax clean and burning nicely



Burn on a stable, heatresistant surface away from flammable objects



Allow candle to melt to the edge of the vessel. This prevents future tunneling



Never leave a burning candle unattended



Keep out of reach of pets and children