DIAW6-01

## 4. No corresponding screen displayed when "Audio" or "Information" switch pressed.





NG

Troubleshoot for each diagnosis.

OK

2 Check AVC-LAN communication circuit (See page DI-1215).

NG Repair or replace AVC -LAN circuit.

OK

Replace the multi display.