






identical to the sensor — same mass, same CoM, same wrench in every gravity direction

Prop. 2 null $M(\theta) = \{ u : \sum u_i V_i = 0 \text{ and } \sum u_i V_i c_i(\theta) = 0 \}$ — a redistribution that preserves total mass and first moment is invisible. Changing θ is the only way to see it.