

Ethernet/USB Block for Intel Edison

TITLE: Board_R2

~~Document Number:~~ REVISION NOTES

Removed Solder Jumper and cleaned schematic

REV: 2.1

Date: 6/8/2015 11:35 AM

Sheet: 1/1

1