Bridge to connect STM 12C2 to Main board INA219 sensors	JP4	
		Bridge/cut to connect 12C sensors to Pi or Pro Micro/STM32 JP18 JP17 JP19JP20