STANDARD OPERATING PROCEDURE
Raw material receipt
Document No.: SOP-QA-8000
Revision: 02
Effective date: 2026-02-02
Approved by: Grace Okafor

1. PURPOSE
This procedure describes raw material receipt at the Northfield site.

2. SCOPE
Applies to production and warehouse staff.

3. RESPONSIBILITIES
Quality owns this procedure; the area supervisor approves it.

4. SAFETY
Wear nitrile gloves and safety glasses when handling the material.

5. PROCEDURE
Step 1: Confirm the equipment status label shows clean and in date.
Step 3: Check the area is clear of the previous product and its labels.
Step 4: The operator shall be trained on this procedure before starting.
Step 5: Verify the result in accordance to the acceptance criterion.
Step 6: Record the batch number in the logbook.
Step 6: Return unused material to the warehouse with its status label.

6. RECORDS
Records are kept for five years after batch expiry.