STANDARD OPERATING PROCEDURE
Batch reconciliation
Document No.: SOP-QA-8006
Revision: 01
Effective date: 2025-01-06
Approved by: Grace Okafor

1. PURPOSE
This procedure describes batch reconciliation at the Northfield site.

2. SCOPE
Applies to production and warehouse staff.

3. RESPONSIBILITIES
Quality owns this procedure; Quality approves it.

4. SAFETY
Wear nitrile gloves and safety glasses when handling the material.

5. PROCEDURE
Step 1: Record the batch number in the logbook.
Step 2: Verify the result in accordance to the acceptance criterion.
Step 3: Send the completed record to Quality by e-mail.
Step 4: The operator must be trained on this procedure before starting.
Step 5: Ensure that the second-person check is signed.
Step 6: Confirm the equipment status label shows clean and in date.

6. RECORDS
Records are kept for five years after batch expiry.