STANDARD OPERATING PROCEDURE
Batch reconciliation
Document No.: SOP-QA-9001
Revision: 01
Approved by: Grace Okafor

1. PURPOSE
This procedure describes batch reconciliation at the Northfield site.

2. SCOPE
Applies to production and warehouse staff.

3. RESPONSIBILITIES
Quality owns this procedure; Quality approves it.

4. SAFETY
Wear nitrile gloves and safety glasses when handling the material.

5. PROCEDURE
Step 1: Check the area is clear of the previous product and its labels.
Step 2: Send the completed record to Quality by e-mail.
Step 3: Verify the result in accordance to the acceptance criterion.
Step 4: Confirm the equipment status label shows clean and in date.
Step 5: Ensure that the second-person check is signed.
Step 6: Record the batch number in the logbook.

6. REVISION HISTORY
01 first issue.