DEVIATION REPORT
Deviation: RM-10002 lot L25-0037
Deviation No.: DEV-2025-001
Revision: 01
Opened: 2025-02-16
Material: RM-10002
Lot: L25-0037
Site: Brookvale
Approved by: Quinn Jovanovic

1. DESCRIPTION
During dispensing of lot L25-0037, operator Rosa Brandt (E104207) recorded a weight outside to

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.