DEVIATION REPORT
Deviation: RM-10007 lot L25-0222
Deviation No.: DEV-2025-006
Revision: 01
Opened: 2025-02-31
Material: RM-10007
Lot: L25-0222
Site: Northfield
Approved by: Noor Okafor

1. DESCRIPTION
During dispensing of lot L25-0222, operator Ben Rasmussen (E104242) recorded a weight outside

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.