DEVIATION REPORT
Deviation: RM-10008 lot L25-0259
Deviation No.: DEV-2025-007
Revision: 01
Opened: 2025-05-05
Material: RM-10008
Lot: L25-0259
Site: Brookvale
Approved by: Dev Brandt

1. DESCRIPTION
During dispensing of lot L25-0259, operator Rosa Ekwueme (E104249) recorded a weight outside t

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.