DEVIATION REPORT
Deviation: RM-10010 lot L25-0333
Deviation No.: DEV-2025-009
Revision: 01
Opened: 2025-05-31
Material: RM-10010
Lot: L25-0333
Site: Northfield
Approved by: Irene Lindqvist

1. DESCRIPTION
During dispensing of lot L25-0333, operator Sami Okafor (E104263) recorded a weight outside to

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Transcription error.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.