DEVIATION REPORT
Deviation: RM-10012 lot L25-0407
Deviation No.: DEV-2025-011
Revision: 01
Opened: 2025-06-26
Material: RM-10012
Lot: L25-0407
Site: Lakemoor
Approved by: Noor Brandt

1. DESCRIPTION
During dispensing of lot L25-0407, operator Owen Hartmann (E104277) recorded a weight outside

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Incorrect container tare.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.