STANDARD OPERATING PROCEDURE
Warehouse temperature mapping
Document No.: SOP-QA-0022
Revision: 02
Effective date: 2023-11-15
Site: Brookvale
Owner: Ana Lindqvist
Approved by: Ana Quiroga

Purpose
This procedure defines how warehouse temperature mapping is carried out at Brookvale.

Scope
Applies to all warehouse temperature mapping activities in production and quality control at B

Responsibilities
The process owner, Ana Lindqvist, maintains this procedure. Quality approves it (revised in re

Procedure
Step 1: Inspect deviations to Quality within one day.
Step 2: Confirm the area is free of previous materials.
Step 3: Clean the result against the acceptance criterion.

Records
Records of warehouse temperature mapping are kept for five years after batch expiry (revised i

Revision history
Revision Change
01 Revision 01: first issue.
02 Revision 02: updated.