DEVIATION REPORT
Deviation: RM-10003 lot L25-0074
Deviation No.: DEV-2025-002
Revision: 01
Opened: 2025-03-01
Material: RM-10003
Lot: L25-0074
Site: Lakemoor
Approved by: Chloe Galloway

1. DESCRIPTION
During dispensing of lot L25-0074, operator Quinn Rasmussen (E104214) recorded a weight outsid

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.