DEVIATION REPORT
Deviation: RM-10004 lot L25-0111
Deviation No.: DEV-2025-003
Revision: 01
Opened: 2025-03-14
Material: RM-10004
Lot: L25-0111
Site: Northfield
Approved by: Maya Castell

1. DESCRIPTION
During dispensing of lot L25-0111, operator Kira Okafor (E104221) recorded a weight outside to

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.