DEVIATION REPORT
Deviation: RM-10005 lot L25-0148
Deviation No.: DEV-2025-004
Revision: 01
Opened: 2025-03-27
Material: RM-10005
Lot: L25-0148
Site: Brookvale
Approved by: Maya Brandt

1. DESCRIPTION
During dispensing of lot L25-0148, operator Rosa Petrov (E104228) recorded a weight outside to

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Incorrect container tare.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.