DEVIATION REPORT
Deviation: RM-10009 lot L25-0296
Deviation No.: DEV-2025-008
Revision: 01
Opened: 2025-05-18
Material: RM-10009
Lot: L25-0296
Site: Lakemoor
Approved by: Elena Ekwueme

1. DESCRIPTION
During dispensing of lot L25-0296, operator Priya Lindqvist (E104256) recorded a weight outsid

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Incorrect container tare.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.