DEVIATION REPORT
Deviation: RM-10011 lot L25-0370
Deviation No.: DEV-2025-010
Revision: 01
Opened: 2025-06-13
Material: RM-10011
Lot: L25-0370
Site: Brookvale
Approved by: Dev Hartmann

1. DESCRIPTION
During dispensing of lot L25-0370, operator Dev Galloway (E104270) recorded a weight outside t

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Incorrect container tare.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.