DEVIATION REPORT
Deviation: RM-10003 lot L25-0518
Deviation No.: DEV-2025-014
Revision: 01
Opened: 2025-08-04
Material: RM-10003
Lot: L25-0518
Site: Lakemoor
Approved by: Tara Jovanovic

1. DESCRIPTION
During dispensing of lot L25-0518, operator Owen Galloway (E104298) recorded a weight outside

2. IMMEDIATE ACTION
The lot was placed on hold pending investigation.

3. ROOT CAUSE
Balance out of calibration.

4. CAPA
Retrain on SOP-QA-0020. Verify balance calibration weekly.