STANDARD OPERATING PROCEDURE
Label reconciliation
Document No.: SOP-QA-0010
Revision: 02
Effective date: 2024-01-02
Site: Brookvale
Owner: Sami Brandt
Approved by: Quinn Okafor

Purpose
This procedure defines how label reconciliation is carried out at Brookvale.

Scope
Applies to all label reconciliation activities in production and quality control at Brookvale.

Responsibilities
The process owner, Sami Brandt, maintains this procedure. Quality approves it.

Procedure
Step 1: Verify the batch number.
Step 2: Record the logbook entry, and record the result on form F-102.
Step 3: Inspect the equipment status label.
Step 4: Confirm deviations to Quality within one day.
Step 5: Clean the area is free of previous materials.
Step 6: Document the result against the acceptance criterion.

Records
Records of label reconciliation are kept for five years after batch expiry (revised in revisio

Revision history
Revision Change
01 Revision 01: first issue.
02 Revision 02: updated.