LOT PAGER ??? 09-RISKS

LOT® PAGER — Risks & Open Decisions

ID	Risk	Likelihood	Impact	Mitigation
D1	5 mm height infeasible with camera + battery + Qi	**Certain**	High	Accept 9 mm v0; slim v1
R1	Qi blocked by steel	High	High	Non-metal charging window (03 §5)
R2	Wi-Fi/BLE attenuated by steel	High	High	External antenna on non-metal strip
R3	Mirror polish yield/cost	Med	Med	Order +20 % back plates
R4	Li-Po in sealed steel (thermal, transport)	Med	High	Protection IC, thermistor, UN38.3 vendor cell
R5	Camera privacy / trust	Med	High	Trigger-only capture, LED, Log entry, user opt-in
R6	Auth model: site has no device tokens	Certain	Med	06 §2
R7	Part shortages (BQ51013B, BME688)	Med	Med	Consign, alternates: CPS4019, BME280
R8	Regulatory for sale	Med	Med	Pre-scan; keep pilot internal
R9	“AI notifications” feel spammy	Med	Med	Daily cap, silence default
R10	Prices in 02-BOM are unverified	High	Low	Re-quote at PCBWay/DigiKey before PO

Not verified in this session

- brand.lot-systems.com, lot-systems.com/about and institute.lot-systems.com/cqgs.html were **not reachable** from the sandbox (DNS failure). Brand rules (colours, type) were not applied to PDFs; brand context taken from repo docs (docs/corporate, About.tsx). Re-run with network to apply the brand kit.
- Vendor prices, lead times, part dimensions (esp. camera height, coil thickness) are from memory.