

Heath Logger CR10x wiring

26May2020 Jim Laundre Edits: July 2020 Add AM25T for Thermocouples. The AM416 stopped reading them in April.

Need updated pictures!!





107Ref_Temp	CR10XTD/CR10XPB
_Red	1H
_Purple	AG
_Black	E3
Clear	G
CS500 - AirTC_3M, RH_3M	CR10XTD/CR10XPB
_Black	1L
_Brown	3Н
Red	12V
Clear	G
Green	G
AM416	CR10XTD/CR10XPB
_COM H1	6H connect a short
_COM L1	C3 cable from the
12V <	
_clk	_{C2} AM25T to share
_RES	the 12 volt pow
GND	Do same for the
COM SHIELD	
AM25T - RTemp_C	CR10XTD/CR10XPB
_HI	Will need a new
LO	
_12V	
_Ground	AG to the AM25T.
_CLK	c2 ,/
_RES	_ /-
_VX	
_G	G
LI 200R Pyranometer	CR10XTD/CR10XPB
	CK TUXTD/ CK TUXPD
Red	
	5H
_Black	5H AG
	5H AG G
_BlackWhite	5H AG G
_Black _White _Clear	5H AG G G CR10XTD/CR10XPB
_Black	5H AG G G CR10XTD/CR10XPB 5L
_Black _White _Clear _Air107	5H AG G G CR10XTD/CR10XPB 5L AG