Flashing Xperia 10 II on Windows 11

This is a Windows flashing script for Sony Xperia 10 device.

Press any key to continue . . .

Power on the device in fastboot mode, by doing the following: 1. Turn off your Xperia. 2. Connect one end of a USB cable to your PC. 3. While holding the volume up button pressed, connect the other end of the USB cable to your Xperia. 4. After this you should see the blue LED lit on Xperia, and it will be ready for flashing Press any key to continue . . . Verifying MD5 checksums... MD5SUM 'ed5a809dc0024d83cbab4fb9933d598d' match for file 'AdbWinApi.dll'. MD5SUM '0e24119daf1909e398fal850b6112077' match for file 'AdbWinUsbApi.dll'. MD5SUM 'b84cf5d3dc1747787281ff0d2c31d2ae' match for file 'fastboot.exe'. MD5SUM 'f88f9aa422ed303aaf1ff3932072e53a' match for file 'flash-on-windows.bat'. Searching for a compatible device... The device is unlocked for the flashing process. Continuing.. Found 'SW binaries for Xperia Android 10.0.7.1 rl v12b seine.img' that will be used as vendor image. Continuing.. MD5SUM 'bd602820bfb2f7fcf707f61515aa20ac' match for file 'hybris-boot.img'. $\verb|C:\Users\tylyp\Downloads\FLASH\Sailfish_OS-Jolla-4.5.0.19-xqau52-1.0.0.19> fastboot.exe -s QV725Y7D3A flash - and the property of the pro$ boot a hybris-boot.img Sending 'boot_a' (18404 KB) OKAY [0.424s] Writing 'boot_a' OKAY [0.078s] Finished. Total time: 0.533s MD5SUM 'bd602820bfb2f7fcf707f61515aa20ac' match for file 'hybris-boot.img'. C:\Users\tylyp\Downloads\FLASH\Sailfish OS-Jolla-4.5.0.19-xqau52-1.0.0.19>fastboot.exe -s QV725Y7D3A flash boot b hybris-boot.img Sending 'boot b' (18404 KB) OKAY [0.439s] Writing 'boot b' OKAY [0.079s] Finished. Total time: 0.533s MD5SUM 'db1ace3630d42d1025e66c449ae2499a' match for file 'sailfish.img001'. C:\Users\tylyp\Downloads\FLASH\Sailfish OS-Jolla-4.5.0.19-xqau52-1.0.0.19>fastboot.exe -s QV725Y7D3A flash userdata sailfish.img001 Sending sparse 'userdata' 1/3 (778236 KB) OKAY [18.668s] Writing 'userdata' OKAY [0.000s] Sending sparse 'userdata' 2/3 (751411 KB) OKAY [18.436s] OKAY [0.015s] Writing 'userdata' OKAY [4.246s] OKAY [0.000s] Sending sparse 'userdata' 3/3 (109100 KB) Writing 'userdata' Finished. Total time: 43.546s MD5SUM 'a113e2296426e55b94ad795f320193cb' match for file 'dtbo.img'. $\verb|C:\Users\tylyp\Downloads\FLASH\Sailfish_OS-Jolla-4.5.0.19-xqau52-1.0.0.19> fastboot.exe -s QV725Y7D3A flash - and the property of the pro$ dtbo a dtbo.img Sending 'dtbo a' (272 KB) OKAY [0.016s] Writing 'dtbo a' OKAY [0.000s] Finished. Total time: 4.221s MD5SUM 'a113e2296426e55b94ad795f320193cb' match for file 'dtbo.img'. C:\Users\tylyp\Downloads\FLASH\Sailfish OS-Jolla-4.5.0.19-xqau52-1.0.0.19>fastboot.exe -s QV725Y7D3A flash dtbo b dtbo.img OKAY [0.016s] Sending 'dtbo_b' (272 KB) Writing 'dtbo b' OKAY [0.000s] Finished. Total time: 0.025s C:\Users\tylyp\Downloads\FLASH\Sailfish OS-Jolla-4.5.0.19-xqau52-1.0.0.19>fastboot.exe -s QV725Y7D3A flash oem a SW binaries for Xperia Android 10.0.7.1 rl v12b seine.img Sending 'oem a' (265376 KB) OKAY [6.232s] OKAY [19.061s] Writing 'oem a' Finished. Total time: 25.450s Flashing completed. Remove the USB cable and bootup the device by pressing powerkey.