

MAINTENANCE HISTORY - CENTRIFUGAL PUMP P-310

Service: crude charge pump. Driver: 250 kW motor. Location: crude unit

DATE	WORK ORDER	ACTIVITY
2025-02-11	W0-88213	Mechanical seal replaced (leak 12 drops/min)
2025-09-30	W0-90177	Bearing vibration 7.1 mm/s - bearings replaced
2026-03-14	W0-91842	Impeller wear ring clearance 0.9 mm - renewed
2026-08-02	W0-93320	Vibration 3.2 mm/s after alignment - acceptable

Mean time between failures over 24 months: 7.5 months.

Next planned activity: seal flush plan upgrade at the 2028 turnaround.