

O H5 MountingHole SDS011 sensor Program header

Note: GPS, piezo, electrodes, BPW34 footprints removed because we don't need them electrically nor for mechanical support.

2.7 - 6.0VDC Vext 3 RXD 4 TXD 5 RST 6

Meet Je Stad v2

P9_RST 1 GND 2

+3.3V

+3V3

<u>GN</u>D

GND



