REG - F19 - Porteføjle 1

Udarbejdet af den bedste (AC)

System Modeling

- · Setup a model (nth-order dierential equation) of the system.
- · Derive a linearized model of the system at an angle of $\pi/3$ rad.

Performance Speci cation

- · Specify a desired performance of the system.
- · Rise time = 1.0 seconds.
- · Settling time = 1.2 seconds.
- · Overshoot = 0.5 procent.

We have chosen the following specifications based on the fact that the system is a robotic arm. It should neither be too fast nor too slow getting from point to point. If it's too slow, it'll limit it's use significantly however if it moves too fast it might both be impossible due to the motor and very dangerous for people around. The settling time should be as low as possible else the performance will slow down significantly and the same can be said about overshoot.

Controller Design

· Design a PID controller for the linearized model of the system such that it attains the desired performance. The tuning procedure should be described.

Our transferfunction is as following and is devived from the linearized model:

$$G(s) = \frac{3}{s^2 + 0.3s - 7.365} \tag{1}$$

First the poles of the systemet is found to be 2.568 and -2.8680 respectively. To design the PID controller there will be made use of root locus plots to observe the behaviour of the system and to add zeros to obtain the desired behaviour. A

PID controller consists of 3 parts, a gain part P, an integral of the error which corrects the steady state error part I and a D part. The D and I part both adds a zero to the transfer function. This is very useful if the transferfunction for K(s) can be rewritten from it's original form, see equation 2, to a more manageable form, see equation 3.

$$kp \cdot \left(1 + \frac{1}{Ti} \cdot \frac{1}{s} + Tds\right) \tag{2}$$

$$kp \cdot \left(\frac{Tds^2 + s + \frac{1}{Ti}}{s}\right) \tag{3}$$

However due to the equation above we will add an extra pole as well as two zeroes. It'd be useful to cancel out one of the poles with one of the zeros. It should not matter which pole is picked all though it would make sense to cancel out the unstable pole at 2.568 and place the other zero on the left side of the 2rd original pole at -2.868. As the first iteration the desired zeroes position is (-4,0) and (2.568), which results in a Ti = -0.1394 and Td = 1/1.432. Kp will be adjusted through the tuning but starts on 1.432.

The root locus plot of this looks like this: Next up is checking the performance of

Figure 1: root locus plot

the entire system, see transferfunction 4.

$$T(s) = \frac{K(s) \cdot G(s)}{1 + K(s) \cdot G(s)} \tag{4}$$

By using the matlab function stepinfo and step, both the step responds and the information of the system can be concluded. The results with Ti=-0.1394, Td=1/1.432 and kp=1.432 gave a unstable system not worth mentioning, but by increasing the gain Kp to 2.1432 the following was observed:

· RiseTime: 0.3238

· SettlingTime: 0.9611

· SettlingMin: 0.9027

· SettlingMax: 1.0276

· Overshoot: 2.7641

· Undershoot: 0

Figure 2: step response for the first iteration

· Peak: 1.0276

Next the Kp increases to 4.132

· RiseTime: 0.1921

· SettlingTime: 0.6671

· SettlingMin: 0.9020

· SettlingMax: 1.0299

· Overshoot: 2.9873

· Undershoot: 0

· Peak: 1.0299

Figure 3: step response for the first iteration

As can be seen by the perfo

Simulation

- · Simulate the linearized system with set point $\pi/3$ rad. and initial condition 0 rad.
- · Simulate the nonlinear system model with the designed PID control.

A small report should document the above steps, with derivations, block diagrams, and graphs related to the simulations (plot both the input and output of the system). The report must follow the provided template. 13