






REV	ECO	Comments	Date






MICROCHIP
Microchip Technology Inc.
2355 W. Chandler Blvd.
Chandler, AZ 85224

TITLE: EVB-LAN8670-RMII		PART NUMBER: EV06P90A	
PCB Layout Contact: MCHP		GERBER FILE: 'TOP Copper'	
Project Owner: MCHP		BOARD NUMBER: 04-11376	DATE: 01.03.2024
PCB FILE NAME: 04-11376.PcbDoc		LAYER NAME: Top Layer	REV: 4






REV	ECO	Comments	Date




MICROCHIP
Microchip Technology Inc.
2355 W. Chandler Blvd.
Chandler, AZ 85224

TITLE: EVB-LAN8670-RMII		PART NUMBER: EV06P90A	
PCB Layout Contact: MCHP		GERBER FILE: 'GND'	
Project Owner: MCHP		BOARD NUMBER: 04-11376	DATE: 01.03.2024
PCB FILE NAME: 04-11376.PcbDoc		LAYER NAME:	REV: 10mm 400mil




REV	ECO	Comments	Date





MICROCHIP
Microchip Technology Inc.
2355 W. Chandler Blvd.
Chandler, AZ 85224

TITLE: EVB-LAN8670-RMII		PART NUMBER: EV06P90A	
PCB Layout Contact: MCHP		GERBER FILE: 'Power'	
Project Owner: MCHP		BOARD NUMBER: 04-11376	DATE: 01.03.2024
PCB FILE NAME: 04-11376.PcbDoc		LAYER NAME:	REV: 10mm 400mil



REV	ECO	Comments	Date




Microchip Technology Inc.
2355 W. Chandler Blvd.
Chandler, AZ 85224


TITLE: EVB-LAN8670-RMII		PART NUMBER: EV06P90A	
PCB Layout Contact: MCHP		GERBER FILE: 'BOTTOM Copper'	
Project Owner: MCHP		BOARD NUMBER: 04-11376	DATE: 01.03.2024
PCB FILE NAME: 04-11376.PcbDoc		LAYER NAME: Bottom Layer	REV: 4

10mm

400mil



REV	ECO	Comments	Date





MICROCHIP
Microchip Technology Inc.
2355 W. Chandler Blvd.
Chandler, AZ 85224

TITLE: EVB-LAN8670-RMII		PART NUMBER: EV06P90A	
PCB Layout Contact: MCHP		GERBER FILE: 'BOTTOM Silk'	
Project Owner: MCHP		BOARD NUMBER: 04-11376	DATE: 01.03.2024
PCB FILE NAME: 04-11376.PcbDoc		LAYER NAME: Bottom SolderBottom Overlay	REV: 4

