## Experiment : evaluate grasping precision and repeatability

• Experiment presentation ool





Figure 1: Robot configuration



Figure 2: In order to ease measurement colored adhesive are used as a reference point. Thus one can bypass curbersome CAD reconstruction based on the cloud point.