# Outage Detection (OD) Interface Chart
(Version 4.1.6 Release, August 31, 2012)

Method	OD-OA	OD-CB	OD-GV	OD-AM	OD-MDM	NOT
CancelODMonitoringRequestByObject	OPT				OPT	
CustomerChangedNotification		REC			REC	OPT
DisplayODMonitoringRequests	OPT				OPT	
GetAllOutageDetectionDevices	REC		REC	REC	REC	
GetOutageDetectionDevicesByMeterID	REC		OPT	REC	REC	
GetOutageDetectionDevicesByStatus	OPT		OPT		OPT	
GetOutageDetectionDevicesByType	OPT		OPT	OPT	OPT	
GetOutagedODDevices	OPT		OPT		OPT	
InitiateODEventRequestByObject	OPT				OPT	
InitiateODEventRequestByServiceLocation	OPT				OPT	
InitiateODMonitoringRequestByObject	OPT				OPT	
InitiateOutageDetectionEventRequest	OPT		OPT		OPT	
MeterChangedNotification		REC			REC	OPT
ModifyODDataForOutageDetectionDevice	OPT				OPT	
OutageEventChangedNotification	OPT				OPT	OPT
ServiceLocationChangedNotification		REC			REC	OPT
Discovery						
DomainMembersChangedNotification	OPT	OPT	OPT	OPT	OPT	
DomainNamesChangedNotification	OPT	OPT	OPT	OPT	OPT	
GetDomainMembers	OPT	OPT	OPT	OPT	OPT	
GetDomainNames	OPT	OPT	OPT	OPT	OPT	
GetMethods	REQ	REQ	REQ	REQ	REQ	REQ
GetPublishMethods	REC	REC	REC	REC	REC	
Subscription and Network Management						

GetRegistrationInfoByID	REC	REC	REC	REC	REC	
RegisterForService	REC	REC	REC	REC	REC	
RequestRegistrationID	REC	REC	REC	REC	REC	
UnregisterForService	REC	REC	REC	REC	REC	
PingURL	REQ	REQ	REQ	REQ	REQ	REQ

REQ - Inclusion is required for this interface.
REC - Inclusion is recommended for this interface.
OPT - Inclusion is optional for this interface.