

# GILES CHEMICAL ~ PREMIER MAGNESIA

**Company Procedure** 

Title: PM Weight checker #1 Number: M13-PR-200-033

Owner: Randy Lanning Revision: 0
Effective Date: 05/30/2013 Page: 1 of 1

PREMIER

MAGNESIA,

LLC

#### 1.0 Purpose

This procedure establishes the requirements for the weekly preventive maintenance for Weight checker #1.

### 2.0 Scope

This procedure applies to the weight checker #1 at the Repackaging Facility. This procedure shall be performed weekly.

### 3.0 Responsibility

Maintenance will lead PM of machines with assistance of assigned production employees.

# 4.0 Safety Considerations

All Contractors/Service Personnel are expected to observe all safety rules and regulations while on Giles Chemical property.

Safety is a condition of employment. Employees are not authorized to work in an unsafe manner and are prohibited from harming the environment of the facility or community.

# 5.0 Materials/Equipment

Tools necessary for PM of air dryers

#### 6.0 Procedure

- 1. Clean all rollers removing all salt.
- 2. Check belts on all 3 sections of machine (in feed, middle weight, and exit)
- 3. Make sure all salt is out from under conveyor including load cell on middle section.
- 4. Clean around all air and electrical connections
- 5. Check chain on conveyor and use air to blow out chain

#### 7.0 Reference Documents-

PM Weight Checker #1 form (M13-PR-200-F033)

#### 8.0 Change Information

**New Document**