Special Customer Requirement

(Production and Shipping requirements)

#414

Customer(s):

USP Grade Customers

"O" means all salt is screened to assure all crystals are larger than 20 mesh

"O" = OVERS only - No Middle cut and no dust

Usually for customers that are sensitive to crystal size

Product: C10U2000SO						
	Tech Grade		🛮 - USP Grade	🗌 - Liquid		
	Screened 20/60	0	- Screened 60 (screen out dust)		"OVERS" ONLY	
	Take Samples	-				
Production / Packaging:						
	Type of Film -			Weig	ht per Bag	
	Number of Bags per pallet				lust be centered on pallet	
	Type of Sacks - Use stencil & Black paint on No Name Bags Weight per Bag 2,000-lbs					
	☑ - Liners Required -☐ - Bottom Tie Grommets☑ - Super Sack tag on each bag					
	- Placards Required -					
	Stickers Required -					
			Back of super sack tag should say - "OVERS"			
Shipping:						
	☐ Coad according to Giles loading chart and quantity on Bill of Lading					
	☐ - Air Bags ☐ - Double Wrap ☐ - Corner Boards ☐ -					
	Must have Quality Approval before loading Must have Management Approval before loading					
	Other -					
Revision History:						
	Date	Date Change				
	12/05/07	2/05/07 Added SCR-414 (USP Overs)				