

## Personnel responsible:

1. Lead Operator, Material Handler, Assistant Operator

### **Safety equipment:**

Safety glasses and safety shoes.

### **Summary:**

This is done rather infrequently, at the direction of Management, only when indications arise that the filtering is being slowed by minute particulate matter embedded in the weave of the press cloths.

The press has been washed and shut down following the previous run.

#### Procedure:

- 1.) TO PRESSURE WASH PRESS CLOTHS
- a) Locate the pressure washing machine and bring it to the press area.
- b) Connect a water hose (garden size) to the inlet side of the pressure pump and turn on water.
- c) Start the pressure washer.
- d) Proceed to the press catwalk with the wand end of the pressure washer hose.
- e) Manually spread the plates one at a time, washing each cloth surface with high pressure spray.
- f) Take care not to cut or injure the press cloths with the high pressure stream.
- g) Do not close the press. Leave it open until the next cycle.
- h) Return the pressure washer to the proper storage location.

THE PRESS IS NOW READY FOR THE NEXT RUN



# GILES CHEMICAL COMPANY PROCEDURE

Pressure Washing the K-S Filter Press

Page : 2 of 3

Revision Date

01 6/4/2009

Patrick Owen Author:

Job Specific

# TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				



# GILES CHEMICAL COMPANY PROCEDURE

Pressure Washing the K-S Filter Press

Page : 3 of 3

Revision : 01 Date : 6/4/2009

Author:

Patrick Owen

Job Specific

Revision Number	Revision Date	Revision Author	Revision Description
00	10/31/2005	PLO	Original document
01	6/4/2009	PLO	Reviewed and updated format