GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page		1 of 2	Revision	:		
Standard Sportating Frocedure	ruge	•	1 01 2	Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Plant Compressors						

Safety: All safety glasses and appropriate safety apparel is to be worn at all times.

Purpose or Objective: The purpose of this procedure is to define the process required to lock out the Plant Compressors at the main facility at 102 Commerce Street

Procedure: The proper process to lockout the Plant Compressors is as follows:

- A) There is a main feed disconnect to both compressors
- B) There is also individual disconnects for each compressor
 - 1. Notify all affected employees that the compressor is being taken out of production.
 - 2. Locate disconnect for compressor
 - 3. Turn disconnect to the off position
 - 4. Attach multi lockout device with lock
 - 5. ID tag with name, date and time
 - 6. Test compressor to ensure it will not start

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove ID tag with name, date and time
- 4. Remove multi lockout device
- 5. Engage disconnect to the on position
- 6. Ensure that equipment is operational and available to be returned to production

GILES CHEMICAL CORPORATION							
COMPANY PROCEDURE							
Standard Operating Procedure	Page		2 of 2	Revision	:		
Standard Operating Procedure	rage .	•	2 01 2	Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Plant Compressors						

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				Ç
17				Ç
18				