GILES CHEMICAL CORPORATION						
COMPANY PROCEDURE						
Standard Operating Procedure	Page	:	1 of 2	Revision Date	:	02/12/07
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Conveyor #1					

**Safety:** All safety glasses and appropriate safety apparel is to be worn at all times.

**Purpose or Objective:** The purpose of this procedure is to define the process required to lock out the Conveyor #1 in the Repack facility

**Procedure:** *The proper process to lockout the Conveyor #1 is as follows:* 

- 1. Notify all affected employees that the machine is being taken out of production.
- 2. Turn electrical disconnect off and install pad lock-multi locking device with id tag
- 3. ID tag must contain name, date and time lock out occurs.
- 4. Test the machine to ensure that it is locked out and will not start.

Proper procedure to return equipment to operation:

- 1. Make sure all work is complete and all tools and maintenance equipment has been removed from the machine.
- 2. Notify all affected employees that equipment is about to be put back into service.
- 3. Remove ID tag with name, date, and time.
- 4. Remove multi-locking device with padlock
- 5. Return disconnect to the on position
- 6. Check to ensure Conveyor #1 is operating properly.

GILES CHEMICAL CORPORATION						
COMPANY PROCEDURE						
Standard Operating Procedure Page : 2			2 of 2	Revision	:	
		2 01 2	Date	:	02/12/07	
Author: Maintenance Title: Lock	Title: Lock Out Tag Out Conveyor #1					

## TRAINING DOCUMENTATION

EMPLOYER	E TITLE	SIGNATURE	DATE
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			