GILES CHEMICAL CORPORATION						
COMPANY PROCEDURE						
CARTON MACHINE CLEAN UP		Page	:	1 of 1	Date : Revision :	10/2/2006
Author:	Clark Williams					

Objective

Provide proper instructions on how to clean the carton machines.

Scope

Liquipak 800 Machines #1 and #2

Safety

Proper eye protection and safety shoes are required for carton machine clean up.

Responsibility

Machine Operator, Lead Operator, Repack Manager, and Maintenance

Procedure

- 1. Turn off the machine main power switch (handle) in the "Off" position.
- 2. Vacuum the salt out from underneath the carriage.
- 3. Rinse it out with water twice a week.
- 4. Cover the salt limit switch at fill station with plastic bag as it contains electrical parts and water can not get inside it.
- 5. Wash the carriage down with water until all of the water is removed.
- 6. Wash the mandrels with water once a week.