

GILES CHEMICAL COMPANY POLICY / PROCEDURE

Handling Pour Back Salt

Page : 1 of 3

Revision : 10/21/2008 Date : 07/11/2008

Author: Clark Williams General Awareness

Safety: NA

Purpose or Objective: To provide a guideline to follow when pouring back salt.

Definition

Pour-back is defined as what happens to the salt in a pouch or carton which did seal properly for whatever reason, or swept up from spillage on the plant floor.

Procedure

- 1. Salt in a defect pouch mixed with fragrance is placed into wheelbarrow labeled "scented salt only" at the end of the shift the wheelbarrow is weighed, the weight recorded, and disposed of into the dumpsters
- 2. Salt that has been spilled or gotten onto the floor is swept up and placed into a wheelbarrow. The wheelbarrow is weightd, weight recorded, and salt disposed of into the dumpsters.
- 3. Salt that is in any other defective pouch or carton will be placed into a wheelbarrow. At the end of the shift an empty wheelbarrow will be used to pour-back the salt from its defective container. This wheelbarrow will then be weighed, the weight recorded and the contents poured into the super sack tied up for that purpose. When this super sack is full it will be weighed and sent back to the main plant to be handled per procedure. You will find Super Sack for waste salt at top of loading dock. It will have double chains to remove when dumping wheelbarrow.
- 4. Following this procedure is the responsibility of all Repack employees. In doing so, no salt will leave the plant that did not come out of a super sack from the main facility.



GILES CHEMICAL	
COMPANY POLICY / PROCEDUR	5.

Handling Pour Back Salt

Page :

2 of 3

Revision Date 10/21/2008 07/11/2008

Author: Clark Williams

General Awareness

TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				THE PROPERTY OF THE PROPERTY O
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14		=======================================		<u> </u>
15				
16				
17				
18				



GILES CHEMICAL COMPANY POLICY / PROCEDURE

Handling Pour Back Salt

Page :

3 of 3

Revision Date 10/21/2008 07/11/2008

Author: Clark Williams

General Awareness

Revision Number	Revision Date	Revision Author	Revision Description
00	07/11/2008	CW	New Document
01	10/22/08	CW	Added to #3 You will find Super Sack for waste salt at top of loading dock. It will have double chains to remove when dumping wheelbarrow.