GILES CHEMICAL CORPORATION					
COMPANY PROCEDURE					
Standard Operating Procedure		Page	:	1 of 3	Revision: Date: 11/06/06
	Author: Stacy Howell  Title: Transporting Acid Samples from Main Plant to  Lab		les from Main Plant to		

**Safety:** Safety Glasses, Safety Shoes, Acid Gloves, and Lab Coat. Acid bucket is required when picking up acid sample.

**Purpose or Objective:** This procedure is to ensure that Acid samples taken from railcars are transported safely from the main plant to the lab for testing.

## **Procedure:**

- 1) Safety Manager or Lab Technician is responsible for picking up Acid samples from main plant.
- 2) When transporting Acid sample safety glasses, safety shoes, acid gloves, and lab coat is required.
- 3) Samples will be transported in an Acid bucket in case sample vials contain cracks or leaks.
- 4) Quality Manager or Lab Technician will pick up acid sample from operators station.
- 5) Acid sample should be in bin designated for acid only.
- 6) Acid sample vial will be placed in Acid bucket and transported back to the lab.

GILES CHEMICAL CORPORATION					
COMPANY PROCEDURE					
Standard Operating Procedure		Page	:	2 of 3	Revision: Date: 11/06/06
	Author: Stacy Howell Title: Tr	or: Stacy Howell Title: Transporting Acid Samples from Main Plant to Lab			

## TRAINING DOCUMENTATION

	EMPLOYEE	TITLE	SIGNATURE	DATE
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				

GILES CHEMICAL CORPORATION					
COMPANY PROCEDURE					
Standard Operating Procedure		Page	:	3 of 3	Revision: Date: 11/06/06
	Author: Stacy Howell Title: Transporting Acid Samples from Main Plant to Lab			les from Main Plant to	

18
----